

SCULPTURE MAINTENANCE RECORD

Accession Number:

Artist: Tom Gibbs

Title: SONG OF THE EARTH

Location: UCA, Conway

Component/Materials: Granite Wall

Dimensions:

Date Examined: 9/16/04

By (name): Rally Buta

Date(s) of Maintenance Treatment: 9/16/04

By (name): Rally Buta

Previous Maintenance Treatment: none maintained (last date) 10/16/03
(Indicate method and materials used, if known)

CONDITION SCULPTURE

Discoloration (staining, blanching, darkening . . .) Fabric of Sculpture Surface Finish or Applied Patina
mid portion North side on top band that appears to be lighter Applied Coating(s)

Graffiti Fabric of Sculpture Surface Finish or Applied Patina Applied Coating(s)

Corrosion Activity Fabric of Sculpture Surface Finish or Applied Patina Applied Coating(s)

Foreign Materials (accretions, bird guano . . .)

Physical Damage (worn, abraded, chipped, scratched . . .) Fabric of Sculpture Surface Finish or Applied Patina
Small scraps on the west end north side (3 about one - two inches) Applied Coating(s)
small scrap on surface on mid portion south side west end (possible weed eater)

Cracks/Splits Fabric of Sculpture Surface Finish or Applied Patina Applied Coating(s)
small separation from concrete on far west end, North side, small cracks in granite on top of east end moving to each side

Missing Parts

Other Problems Fabric of Sculpture Surface Finish or Applied Patina Applied Coating(s)

West 1/3 of the wall is loose

SCULPTURE MAINTENANCE RECORD

Accession Number _____
 Artist/Title: Tom Gibbs/SONG OF THE EARTH Component:
 Date of Record: _____

CONDITION**PEDESTAL** Graffiti Accretions Staining Mechanical Damages Cracks Problems with Joints Other Condition Problems**MAINTENANCE STEPS** Washed (Materials/Method) Sculpture Pedestal Application of Protective Coating (Materials/Method) Sculpture Pedestal Other Maintenance Treatment Steps (Materials/Method) Sculpture Pedestal**ADDITIONAL CONDITION ISSUES / COMMENTS ON ONGOING CONDITION / RECOMMENDATIONS**

SCULPTURE MAINTENANCE RECORD

Accession Number:

Artist: Tom Gibbs

Title: SONG OF THE EARTH

Location: UCA, Conway

Component/Materials: Cast Bronze

Dimensions:

Date Examined: 9/16/04

By (name): Rally Bata

Date(s) of Maintenance Treatment: 9/16/04

By (name): Rally Bata

Page 1 of 2

Previous Maintenance Treatment: none maintained (last date) 10/16/03
(Indicate method and materials used, if known)

CONDITION SCULPTURE

Discoloration (staining, blanching, darkening . . .) Fabric of Sculpture Surface Finish or Applied Patina
It seemed a little spotty. I think it is wax build up in the small rough surfaces. Applied Coating(s)

Graffiti Fabric of Sculpture Surface Finish or Applied Patina Applied Coating(s)
None

Corrosion Activity Fabric of Sculpture Surface Finish or Applied Patina Applied Coating(s)
None

Foreign Materials (accretions, bird guano . . .)
bird droppings on top. Traces of insects nest under protrusions

Physical Damage (worn, abraded, chipped, scratched . . .) Fabric of Sculpture Surface Finish or Applied Patina
Rocks where water drains have split apart. Applied Coating(s)

Cracks/Splits Fabric of Sculpture Surface Finish or Applied Patina Applied Coating(s)

Missing Parts

Other Problems Fabric of Sculpture Surface Finish or Applied Patina Applied Coating(s)

Accession Number _____
 Artist/Title: Tom Gibbs/SONG OF THE EARTH Component:
 Date of Record: _____

CONDITION

PEDESTAL

- Graffiti
- Accretions
- Staining
- Mechanical Damages
- Cracks
- Problems with Joints
- Other Condition Problems

MAINTENANCE STEPS

- Washed (Materials/Method)** Sculpture Pedestal
 water and Shalee Basic H (2 caps / bucket)
- Application of Protective Coating (Materials/Method)** Sculpture Pedestal
 one coat of ~~Shalee~~ Johnson's Paste Wax, then buffed out.
- Other Maintenance Treatment Steps (Materials/Method)** Sculpture Pedestal

ADDITIONAL CONDITION ISSUES / COMMENTS ON ONGOING CONDITION / RECOMMENDATIONS

SCULPTURE MAINTENANCE RECORD

Accession Number:

Artist: Tom Gibbs

Title: SONG OF THE EARTH

Location: UCA, Conway

Component/Materials: Painted steel

Dimensions:

Date Examined: 9/16/04

By (name): Rolly Burton

Date(s) of Maintenance Treatment: 9/16/04

By (name): Rolly Burton, Brandon

Page 1 of 2

Previous Maintenance Treatment: none maintained (last date) 10/16/03
(Indicate method and materials used, if known)

CONDITION SCULPTURE

Discoloration (staining, blanching, darkening . . .) Fabric of Sculpture Surface Finish or Applied Patina
water streaks (E) Applied Coating(s)

Graffiti Fabric of Sculpture Surface Finish or Applied Patina Applied Coating(s)

Corrosion Activity Fabric of Sculpture Surface Finish or Applied Patina Applied Coating(s)
chipped paint & Rust

Foreign Materials (accretions, bird guano . . .)
spider nests, grass, bird droppings

Physical Damage (worn, abraded, chipped, scratched ...) Fabric of Sculpture Surface Finish or Applied Patina
A few scratches on base, and some chipped paint on base Applied Coating(s)

Cracks/Splits Fabric of Sculpture Surface Finish or Applied Patina Applied Coating(s)

Missing Parts

Other Problems Fabric of Sculpture Surface Finish or Applied Patina Applied Coating(s)
small paint chips

SCULPTURE MAINTENANCE RECORD

Accession Number _____

Artist/Title: Tom Gibbs/SONG OF THE EARTH

Component: _____

Date of Record: _____


CONDITION**PEDESTAL***looks okay* Graffiti Accretions Staining Mechanical Damages Cracks Problems with Joints Other Condition Problems**MAINTENANCE STEPS**

Washed (Materials/Method) Sculpture Pedestal
Water and Shuklee Basic #, then a good rinse

Application of Protective Coating (Materials/Method) Sculpture Pedestal
One Coat of Johnson's Paste Wax, then polished (buffed)

Other Maintenance Treatment Steps (Materials/Method) Sculpture Pedestal

ADDITIONAL CONDITION ISSUES / COMMENTS ON ONGOING CONDITION / RECOMMENDATIONS



Water streaks

corrosion spot (east side)

Water streaks (east face)

Small paint chip & corrosion spot (north side)

chipped paint Rust spot south west corner

chipped paint - Rust spots (North side)

chipped paint Rust spot in well (west side)

scratch

a little corrosion

chipped paint

scratch